



## AXLES AND SUSPENSION

Fig. 1



1. The label will always be located on the back of the axle on the center of the beam (Fig. 1).
2. Zinc coated u-bolts and nuts, and powder coated tie plates. This will be similar to a few models from a competitor.
3. Lippert powder coats our axles. Powder coating gives a finer, smoother exterior surface.

Fig. 2 - Axle Label Information



Axle Communication - Manufacture date and  
Serial Number information is critical for analysis  
and correction of issues